

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Sub-Committee

TECHNICAL BULLETIN - OCTOBER 1992

033. Rotor Rides

The Health & Safety Executive recently called a meeting to discuss incidents regarding the trapping of passengers' feet between the rotating platform and the side wall of a Rotor ride. This occurred, as a result of unconventional operation, during the raising of the platform at the end of the ride. It was decided that the remedy was mainly operational and the following points were recommended for Appointed Persons to inform their clients :-

- 1) The ride is to be allowed to slow down with the floor in its lowered position. This means that, as the speed of rotation decreases, the passengers slide down the wall to meet the floor. When the drum has completely stopped, ensuring that the passengers' feet are not being forced against the outer drum, the floor can be raised if necessary.
- 2) An instruction sheet, detailing the above, should be made available to the operator at all times and also fixed, in a suitable and permanent way, within view of the operator.
- 3) Any rubber on the side of the drum at passengers' lower leg level is to be removed, to allow feet to slide easily out of the path of the platform.
- 4) Feet positions are to be marked on the platform floor, several inches from the edge, so that passengers are aware of the preferred position to stand.
- 5) It was also noted that, at present, main entrance doors on some rotor devices can be opened whilst the ride is in motion, giving access to the revolving drum. This can be remedied by fitting an electrically sensed, or mechanical, interlock to the gates ensuring that :
 - a) The ride cannot be started with the doors open.
 - b) The doors cannot be opened with the ride in motion.

Appointed Persons should be aware that HSE has noted a potential problem in the lack of door interlocks and suggest that a hazard is reasonably foreseeable.

P.O. BOX NO. 9, BUXTON, DERBYSHIRE. SK17 9XF

TEL: (0298) 77468 FAX: (0298) 70784