

479.

Twist cracking

JC NDT has found cracks on 11 out of 12 twister car foot rest attachment welds on a Twist ride.

The area in which the cracks were found is highlighted in red on the attached Twist ride image (please note the image is not of the actual device in question; this is for reference/illustration purposes only).

The device the cracks were found on was built by Heath Engineering but it is believed that most devices are of a similar design (if not identical as a lot of Twists were built under licence).



Committee Members: Mr. D Inman (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green, Mr. D Cox, Mr. I Davies, Mr. J Shilling, Mr. A Jenkins & Mr. A Hussein

www.naflic.co.uk

Supported By:

