

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Subcommittee

TECHNICAL BULLETIN - JUNE 1994

088. Super Trooper Accident

A serious accident occurred on a Super Trooper ride, built by S E Ward Ltd of Sheffield, while operating in Jersey.

As yet the facts of the occurrence are a little bare but it is known that the restraint bar came open, either by failure of the catch mechanism or by being released by one of the passengers or by not being properly closed at the start of the ride.

The three possibilities listed in the previous paragraph have implications for NAFLIC members and we hope to provide a more detailed bulletin at a later date when the facts are clearer.

Committee Members :- Dr Garry Fawcett (Chairman), Mr Richard Barnes, Mr Bob Nicholls, Mr Les Howson,
Mr Malcolm Tennant, Mr Peter Steffens

© NAFLIC June 1994

P.O. BOX NO. 9, BUXTON, DERBYSHIRE. SK17 9XF
TEL: (0298) 77468 FAX: (0298) 70784