

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Sub-Committee

TECHNICAL BULLETIN - SEPTEMBER 1995

119. Round-Up Accident

In July 1995 a passenger was seriously injured on a "Roundup" ride. It is understood that she placed her leg through a vertical 140mm gap between the cage segments and came into contact with a handrail on the loading platform.

We feel it important to inform, or remind, people of accidents of which we become aware. We realise that we may become repetitive in our comments and, in this case, the hazards involved were subject matter of recent Technical Bulletins numbered 104, 105 and 106.

We advise Appointed Persons to review rides of the Roundup / Meteorite type for the possibility of entrapment / striking hazards. But clearly the potential for hazards of this type should be continuously in mind when examining all passenger carrying amusement devices.

Committee Members :- Dr Garry Fawcett (Chairman), Mr Richard Barnes, Mr Bob Nicholls, Mr Les Howson,
Mr Malcolm Tennant, Mr Peter Steffens

© September 1995

2A GROVE PARADE, BUXTON, DERBYSHIRE. SK17 6AJ
TEL: (01298) 22384 FAX: (01298) 70784