

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN - MARCH 2002

222. Huss Rainbow

We have been made aware of a bulletin issued by Huss Maschinenfabrik in November 2000 in relation to their Rainbow ride. This was headed "Service Letter 11-07". The bulletin pointed out that the connecting structure which connects the gondola to the arm does not have infinite fatigue life.

Some inspection bodies have become aware of fatigue cracking on these rides and will not be surprised by the bulletin.

Huss have a modified design for this connecting structure.

Committee Members :- Dr Garry Fawcett (Chairman), Mr Richard Barnes, Mr Peter Smith, Mr Ian Grant,
Mr David Geary, Mr Steve Parker, Mr Eddy Price and Mr Mike Preston

© March 2002

PO BOX 752, SUNDERLAND, SR3 1XX
TEL: (0191) 5239498 FAX: (0191) 5239498