

# NAFLIC

*National Association For Leisure Industry Certification*

## **Standards & Related Documents Committee**

### **TECHNICAL BULLETIN - AUGUST 2002**

#### **247. Reverchon Spinning Coaster Service Bulletin**

We understand that a Service Bulletin has been issued by Reverchon Industries relating to non-obvious dimensional differences between the wheel clusters on the front and rear axles of the Spinning Coaster.

We are told that controllers may have, on occasion, assembled front and rear wheel clusters the wrong way round, and that Reverchon suggest that there is a link between this and chassis cracking that is known to have occurred.

Refer to Reverchon Industries for more details.

Committee Members :- Dr Garry Fawcett (Chairman), Mr Richard Barnes, Mr Peter Smith, Mr Ian Grant,  
Mr David Geary, Mr Steve Parker, Mr Eddy Price and Mr Mike Preston

© August 2002

PO BOX 752, SUNDERLAND, SR3 1XX  
TEL: (0191) 5239498 FAX: (0191) 5239498