

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

INCIDENT BULLETIN — November 2015

026. Accident on Booster type ride in China

Two tourists were killed in an amusement ride accident in China. It is reported that a Booster style ride started in motion before the restraints were closed. The manufacturer is not known.

<http://www.dailymail.co.uk/news/peoplesdaily/article-3064055/The-shocking-aftermath-two-tourists-plunged-deaths-thrown-Chinese-amusement-park-ride-called-Scream.html>