

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

INCIDENT BULLETIN — November 2015

028. Bumper Boat accident in US

An accident has occurred on a Bumper Boat ride in Phoenix. The boats are petrol powered and one caught fire as the engine was restarted with two boys on board. They both suffered burns.

<http://www.fox10phoenix.com/story/28655957/2015/03/30/2-boys-suffer-serious-burns-after-bumper-boat-fire-at-amusement-park>

Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green, Mr. I Davies,
Mr. D Cox, Mr. M Thirkettle, Mr. J Shilling & Mr. D Inman

www.naflic.co.uk