

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Sub-Committee

TECHNICAL BULLETIN - AUGUST 1992

022. Scream Machine

This bulletin updates Technical Bulletin 012 as a result of further information provided at the meeting of the JAC (Joint Advisory Committee for Health & Safety in the Fairground Industry) held at Preston on 13 August 1992.

The investigation into the accident in which one passenger and a number of passers-by received minor injuries is still under way. The accident resulted from the fatigue failure of one of the radial arms of this "Rock & Roll" type ride. Fatigue occurred at a weld fastening the stub axle into the tubular radial arm. A design review of the region is being undertaken and inspection requirements have been modified.