

101.

Fall from 360° pendulum style ride

We have received a report of a woman falling from a pendulum style fairground ride in Mexico. In a video posted with the report the ride can be seen in operation as it goes through a 360 degree motion, stopping upside down. It is at this point that the woman falls out of her seat but clings on to the ride to avoid dropping to the floor. However, as it swings back down, it throws her off and into barriers at the back of the ride.

At the end of the video, the woman can be seen getting up and standing at the side of the attraction watching as it continues to rotate prior to being brought to a stop. It is not known if the woman sustained any injuries as a result of the incident.

According to local media reports, the accident happened on June 14 at the Kataplum amusement park in Plaza las Antenas in the Mexican city on the Rio Grande.

<https://www.dailymail.co.uk/news/article-7153261/Horrific-moment-woman-falls-fairground-ride-Mexico-sent-flying-rotating-arm.html>

Supported By:

